


2



1





FORMULA
for
RADIUS OF CURVATURE

Let r = radius of bolt circle

Let h = orthogonal distance from screw points to lens surface

Then radius of curvature of lens surface =



$$R = r^2 / 2h + h/2$$



Hole Table			
LOC	XDIM	YDIM	SIZE
1	0.000	0.984	1/4-20 UNC - 1B
2	0.852	-0.492	1/4-20 UNC - 1B
3	-0.852	-0.492	1/4-20 UNC - 1B

Hole Table			
LOC	XDIM	YDIM	SIZE
A1	0.511	0.295	1/4-20 UNC - 1B
A2	0.000	-0.591	1/4-20 UNC - 1B
A3	-0.511	0.295	1/4-20 UNC - 1B

Hole Table			
LOC	XDIM	YDIM	SIZE
1	0.000	0.295	1/4-20 UNC - 1B
2	0.256	-0.148	1/4-20 UNC - 1B
3	-0.256	-0.148	1/4-20 UNC - 1B



Richard J Kinch, PhD -- Palm Beach County, Florida USA -- <http://www.truetex.com>
spherometer_3-leg.idw

2




1

B

B

A

A



Ø1.000

0.152

0.250

r = 11.50 mm

rim

R78.6 mm

EXAMPLE

h = 0.85 mm

0.85 mm

45°

45°

0.500

FORMULA
for
RADIUS OF CURVATURE

Rim diameter =
0.906 [23.00 mm]
(Instrument will
measure lenses of this
diameter or larger.)

Let r = radius of rim
Let h = orthogonal distance from rim to lens surface
Then radius of curvature of lens surface =

$$R = r^2 / 2h + h/2$$

$$R = 11.5\text{mm}^2 / (2 \cdot 0.85\text{mm}) + 0.85\text{mm}/2 = 78 \text{ mm}$$