

SPINDLE AND BASE

Spindle

Base

#10-32 x 1/2  
hex head  
cap screw

$\varnothing 0.205$

4 1/2

1.1°

3/16

1/2

$\varnothing 3/8$

$\varnothing 3/4$

10-32 UNF - 2B

1

$\varnothing 2 1/2$

$\varnothing 0.200$  THRU  
 $\varnothing 0.313 \nabla 0.375$

1/8

1/2

$\varnothing 1/4$

Richard J Kinch, PhD -- Palm Beach County, Florida USA -- <http://www.truetex.com>  
bp\_rocket.idw

2

2

1


B

B

A

A





Richard J Kinch, PhD -- Palm Beach County, Florida USA -- <http://www.truetex.com>  
 bp\_rocket.idw